J. E. STOVER & ASSOCIATES, INC. #3662

2352 NORTH 7th SREET, UNIT B **GRAND JUNCTION, COLORADO 81501** PHONE: (970) 245-4101, FAX 242-7908

MINE ENGINEERING MINE RECLAMATION

CIVIL ENGINEERING CONST. MANAGEMENT



October 14, 2010

Utah Coal Regulatory Program 1594 West North Temple, Suite 1210 Salt Lake City, Utah 84114-5801

Re:

Castle Valley Mining LLC Castle Valley Mines NOV- 10068 Abatement

Permit No. C/015/0025

RECEIVED OCT 19 2010

DIV. OF OIL, GAS & MINING

Dear Sirs:

On behalf of Castle Valley Mining, LLC, attached is an application for a permit change to comply with the abatement actions required by NOV-10068 issued on September 22, 2010.

The referenced notice of violation was written because the Operator failed to submit a permit change or receive Division approval prior to construction of a concrete apron at the end of diversion ditch D-8D, and construction of a valve box for the Culinary Water System. On behalf of Castle Valley Mining, LLC, attached are the revised documents:

As a general note, the 'Water Bar configuration' as described in Chapter-7, page 136 was never constructed. Page 136 details why the water bar was to be constructed but when Ditch D-8D was upgraded with a concrete lining (thus what spurred the NOV) it was discovered by the Operator that the water bar was never installed. In addition, per a phone conversation with Karl Housekeeper on October 12, he confirmed the current configuration consists of Ditch D-8D flowing into a Culvert (newly named Culvert C-14D) and that culvert flows into Sediment Pond B. Reference to the Water Bar has been removed from applicable Plates and permit pages.

Additionally, the location of the new valve box, used to house the controls for the Culinary Water System, was constructed on the north side of the primary shop road.

Changes on applicable permit pages and Plates are detailed on DOGM Form C2. Please feel free to call me if you have any questions.

Sincerely,

J. E. Stover, P.E. Consulting Engineer File in:

☐ Confidential □ Shelf

See Sucoming For additional



APPLICATION FOR COAL PERMIT PROCESSING Detailed Schedule Of Changes to the Mining And Reclamation Plan

Permittee:	Castle Vall	ley Mining LL	С		0.004.510.005			
Mine:	Castle Vall	ley Mines	Permit	Number:	C/015/0025			
Title:	NOV-1006	8 Abatement						
application. of contents,	Individually section of the	list all maps a plan, or other	s to the Mining and Reclamation Plan, which is required as and drawings that are added, replaced, or removed from the rinformation as needed to specifically locate, identify and on and drawing number as part of the description. DESCRIPTION OF MAP, TEXT, OR MATERIA	plan. Includ revise the exi	e changes to the table sting Mining and			
Add [Replace	Remove	Page 7-113, Updated Table 7-24 with new ditch data for I		HANGED			
Add [Replace	Remove	Page 7-119, Added new culvert C-14D					
Add [Replace		Page 7-136, Revised text regarding Ditch D-8D-Water Ba	ır				
Add [Replace		Page 7-138 Water Bar Never Constructed, page will read		onally Left Blank'			
Add	Replace		Page 7G-51, Added Culvert C-14 Design Information, and					
Add [Replace	Remove	Page 7G-52, Added SedCad as program used to size culve	ert				
Add	Replace		Page 7G-108, Added design information for Ditch D-8D,		regarding Water Bar			
Add	Replace		Page 7G-129, Remove Water Bar design, replace SedCad					
X Add	Replace	Remove	Page 7G-107A, Add design for new Culvert C-14D					
Add	Replace	Remove	Page 5A-2, Added new Valve Box to Table 5A-1, Existin	g Structures				
Add	Replace	Remove	Page 5A-10, Added Structure #29, Culinary Water System	Page 5A-10, Added Structure #29, Culinary Water System Valve Box with short description				
Add	Replace	Remove	Plate 5-2B, Added Concrete Lining on Ditch D-8D, Removed Water Bar					
Add	Replace	Remove	Plate 5-2C, Added Valve Box					
Add	Replace	Remove	Plate 7-1C, Added Valve Box					
Add	Replace	Remove	Plate 7-1B, Added C-14D, Concrete lined portion of D-8I	D. Removed \	Water Bar			
Add [Replace	Remove	Plate 7-3, Added C-14D, Removed Grouted inlet text					
	Replace	Remove	Plate 7-5, Added C-14D, Concrete Lining on D-8D, and V	Valve Box. R	emoved Water Bar			
Add	Replace	Remove	Page 8-12, included reclamation estimate for concrete apr	on and concr	ete valve box			
Add	Replace	Remove						
	Replace	Remove						
Add [Replace	Remove						
Add	Replace	Remove						
Add [Replace	Remove						
Add [Replace	Remove						
	Replace	Remove						
Add	Replace	Remove						
	Replace	Remove						
Add [Replace	Remove						
Any other sp Mining and	ecific or spe	cial instructi	on required for insertion of this proposal into the		y Oil, Gas & Mining			
		. T 14411°		R	ECEIVED			
					OCT 1 9 2010			
				DIV. O	FOIL, GAS & MINING			



APPLICATION FOR COAL PERMIT PROCESSING

Permit Chan	ge X New Permit Renewal Exploration Bo	ond Release Tr	ansfer 🗌				
Permittee:	Castle Valley Mining LLC		i				
Mine:	Castle Valley Mines	Permit	Number:	C/015/0025			
Title:	NOV-10068 Abatement						
Description	, Include reason for application and timing required to implement:						
	Mining LLC purchased the mine from the bankruptcy court.						
	If you answer yes to any of the first eight questions, this appl	ication may require I	Public Notice	publication.			
Yes No	Change in the size of the Permit Area? Acres:	Disturbed Area:		increase decrease.			
Yes X No	Is the application submitted as a result of a Division Orce			-			
Yes X No							
Yes X No	, I I						
X Yes No	To the state of th	or increase of insura	nce or reclam	ation bond?			
Yes No	Transfer and the second parties hotico pur		compliance i	nformation?			
Yes X No		emetery or 300 feet	of an occupie	d dwelling?			
X Yes No	이 사람들은 그는 사람들은 아름이 살아가는 사람들이 되었다면 그는 사람들이 아름이 가는 사람들이 되었다면 하는데 그를 보고 있다.	NOV # 10068					
Yes X No	10. Is the application submitted as a result of other laws or r		s?				
	Explain:						
Yes No	**			~			
Yes X No		sign or mine sequence	e and timing?	(Modification of R2P2)			
Yes X No							
	15. Does the application require or include soil removal, sto	etation outside the cu	mrem distarbe	d atca:			
Yes X No	Does the application require or include vegetation moni	toring, removal or re	vegetation ac	tivities?			
X Yes No							
X Yes No	18. Does the application require or include water monitoring	g, sediment or draina	ge control me				
X Yes No	 Does the application require or include certified designs 	, maps or calculation	?				
Yes X No	20. Does the application require or include subsidence contra	rol or monitoring?					
Yes No	21. Have reclamation costs for bonding been provided?			0			
Vas No	22. Does the application involve a perennial stream, a stream	n buffer zone or disc	harges to a st	ream?			
Ves V No	 23. Does the application affect permits issued by other agen 24. Does the application include confidential information at 	cles or permits issue	d to other ent	uies?			
Please attach	three (3) review copies of the application. If the mine is on	or adjacent to Fore	u anu separav st Service Iar	nd nlease submit four			
(4) copies, tha	ank you. (These numbers include a copy for the Price Field Office)	or adjacent to rore	St Str vice in	nu prouse sustaine rour			
I hereby certify th	at I am a responsible official of the applicant and that the information containe	d in this application is true	e and correct to the	he best of my information			
and belief in all re	espects with the laws of Utah in reference to commitments, undertakings, and o	bligations, herein.					
Corey Heaps	Vice President /0-/4-/0	(see He	aps				
Print Name	Position Date Sig	nature (Right-lick aboye	phoose certify th	en have notary sign below)			
Subscribed and sv	worn to before me this 14th day of October , 2010	HIMMERIN K	BISHIM	en have notary sign below)			
Notary Public:	TAMMERIN & BISHOP , state of Walt.	TAL OTAL	0				
My commission I	xpires: 1/22/2011	= 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	(F) = =				
Commission Num	ber: N/A		- /o E				
Address: 100	PRITCHARD MESA CT.	ES: PUBL	10 0 1				
GRAN	10 JCT. State: CO Zip: 81505	11/7 F	ORKILL				
For Office Use	Only:	Assigned Tracking Number:	11111Received	by Oil, Gas & Mining			
		ramoer.	l	RECEIVED			
				OCT 1 9 2010			
			DIV. (OF OIL, GAS & MINING			

PUBLIC NOTICE

Castle Valley Mining, LLC, 2352 N. 7th Street Unit C, Grand Junction, CO, 81501, has submitted an application for a revision to the Division of Oil, Gas and Mining for its Bear Canyon Mine, mining permit No. C/015/0025. The proposed revision contains drainage calculations for a new concrete apron at the end of Ditch D-8D with updated hydrology and surface facilities maps. In addition, the proposed revision includes information relevant to a concrete valve box used to house the controls for the culinary water system and includes updated surface facilities maps noting the location of the concrete box.

The Bear Canyon Mine is located in Bear Canyon, approximately 12 road miles west of Huntington, Utah. The permit area, found on the USGS Hiawatha Quadrangle map, is described as follows:

A. T16S, R7E SLBM Sec. 14: S1/2

Sec. 23:E1/2, E1/2 W1/2

Sec. 24: W1/2, W1/2 E1/2

Sec. 25:NW1/4 NW1/4, E1/2 NW1/4, SW1/4 SW1/4,

E1/2 SW1/4

Sec. 26:NE1/4 NE1/4, NW1/4 NE1/4, N1/2 SW1/4

NE1/4 and the access/haul road and topsoil

storage area as shown on Plate 2-1 of the Bear Canyon

Mining and Reclamation Plan

T16S, R8E SLBM Sec. 7: NE1/4, NE1/4

Sec. 8: NW1/4, W1/4 E1/2, N1/2 SW 1/4, SE1/4 SW1/4

Sec. 16:All Sec. 17:All

Sec. 21:E1/2 NW1/4, NE1/4, N1/2 SE1/4

B. T16S, R7E SLBM Sec. 1: Lots 1 and 2, S1/2 NE1/4, SE1/4

Sec. 10:N1/2, N1/2 S1/2, SE1/4 SW1/4, S1/2 SE1/4

Sec. 11:All Sec. 12:All

Sec. 13:All

Sec. 14:NE1/4, E1/2 NW1/4

Sec. 24:E1/2, E1/2,

Sec. 25:E1/2

T16S, R8E SLBM Sec. 18:SW1/4, SW1/4

Sec. 19:S1/2 NW1/4, SW1/4, SW1/4 SE1/4, N1/2SE1/4,

S1/2 NE1/4

Sec. 20:S1/2 NW1/4, N1/2 SW1/4

Sec. 30:W1/2, W1/2 NE1/4, NW1/4 SE1/4

C. T16S, R7E SLBM Sec.

Sec. 25:SW1/4 NW1/4, NW1/4 SW1/4

T16S, R8E SLBM Sec. 6: Lots 11-14, E1/2 SW1/4, W1/2 SE1/4, SE1/4 SE1/4

Sec. 7: all except NE1/4 NE1/4

Sec. 8: SW1/4, SW1/4

Sec. 18:N1/2, SE1/4, N1/2 SW1/4, SE1/4 SW1/4

D. T16S, R8E SLBM Sec. 31:NE1/4 NW1/4, NW1/4 NE1/4

E. T6S, R8E SLBM Sec. 19:Lot 1, NE1/4 NW1/4, N1/2 NE1/4

Sec. 20: N1/2 NW1/4, NE1/4, NE1/4, NE1/4

Sec. 21: W1/2 NW1/4, N1/2 SW1/2, SE1/4 SW1/4, S1/2SE1/4

Written comments regarding this application may be submitted to and additional information may be obtained from the Utah Division of Oil, Gas & Mining, P. O. Box 145801, Salt Lake City, Utah 84114-5801. Copies of the current mining plan are available for public inspection at the office of the Utah Division of Oil, Gas & Mining, Salt Lake City, and at the Emery County Recorder's Office, Energy County Courthouse, Castle Dale, Utah 84513.

EXISTING STRUCTURES

Table 5A-1 lists each structure and construction dates. Reclamation is expected in 2012

Table 5A-1 Existing Structures
Construction Dates

raction be	2000	
Starting	Completion	Photo #
6/84	10/87	1
10/83	6/84	2
9/82	4/83	3
4/83	7/83	3
6/80	4/84	3
3/80	6/80	3
11/89	12/89	5
10/83	9/84	4
4/80	12/85	6
10/83	12/85	6
3/80	9/84	7
7/04/01	12/31/05	10
9/82	containerized	
8/82	11/82	13
8/92	10/92	15
8/92	10/92	16
5/93	7/94	17
12/93	1/94	18
7/4/01	12/31/05	19
7/4/01	12/31/05	9
7/4/01	12/31/05	12
7/4/01	12/31/05	14
7/4/01	12/31/05	
7/4/01	12/31/05	
7/4/01	12/31/05	
7/4/01	12/31/05	
9	3	
9/10	9/10	
	Starting 6/84 10/83 9/82 4/83 6/80 3/80 11/89 10/83 4/80 10/83 3/80 7/04/01 9/82 8/82 8/92 8/92 5/93 12/93 7/4/01 7/4/01 7/4/01 7/4/01 7/4/01 7/4/01 7/4/01	6/84 10/87 10/83 6/84 9/82 4/83 4/83 7/83 6/80 4/84 3/80 6/80 11/89 12/89 10/83 9/84 4/80 12/85 10/83 12/85 3/80 9/84 7/04/01 12/31/05 9/82 containerized 8/82 11/82 8/92 10/92 8/92 10/92 5/93 7/94 12/93 1/94 7/4/01 12/31/05 7/4/01 12/31/05 7/4/01 12/31/05 7/4/01 12/31/05 7/4/01 12/31/05 7/4/01 12/31/05 7/4/01 12/31/05 7/4/01 12/31/05 7/4/01 12/31/05 7/4/01 12/31/05 7/4/01 12/31/05 7/4/01 12/31/05 7/4/01 12/31/05 7/4/01 12/31/05 7/4/01 12/31/05

5A-2 <u>10/12/10</u>

regulations. The enclosure will be checked weekly and drained of standing water if needed. Details of the design, maintenance, and spill disposal can be found in the C.W. Mining SPCC plan.

28. <u>Portals</u>. The Bear Canyon #3 and #4 Mines, in Wild Horse Ridge, will have a total of six portals (Plate 3-4A and 3-4C), all located in Bear Canyon.

A Summary of the Portals are as follows:

	Existing
Blind Canyon Seam	3
Tank Seam -	<u>3</u>
Total	6

29. Culinary Water System Valve Box: An 8 ft. by 6 ft. concrete box constructed to enclose the control valves for the Culinary Water System. Location of the Box is shown on Plate 5-2C.

5A-10 <u>10/12/10</u>

Table 7-24 Summary of Diversion Ditch Calculations

Ditch	Bottom Width (Ft)	Top Width (Ft)	Depth (Ft)	Type Side Slope H:V	Measured Slope %	Contributing Watershed	REQ'D Av. Rip-Rap Size (In.)
D-1D	0	1.33	0.67	1:1	2 Min 11 Max	AD-3A	Soil
D-2D	0	1.33	0.67	1:1	6 Min 20 Max	AD-3A, AD-5	Bedrock
D-3D					2011107	Replaced with C-5D	
D-4D	0	2	1	1:1	2Min 6Av. 17 Max	AD- 14	Soil Soil D₅0∈ 6"
D-5D					17 Wiax	Replaced with C-5D	DNEU
D-6D	0	3	1.5	1:1	2 Min 4 Max	AD-3A, AD-5 AD-7, AD-9, AD-10 AD-12, AD-14	Soil
D-7D	2	3,5	0.75	1.5:1	2 Min 6 Av. 55 Max	AD-1A, AD-1B, AD-2A AD-2B, AD-2C, AD-3B AD-4, AD-6, AD-8	Soil Soil D ₅₀₌ 6"
D-8D	0	2	1	1:1	2 Min 7 Max	AD-4, AD-6, AD-8 AD-13	Soil
D-8D Concrete	1.5	2.5	0.5	<u>1:1</u>	2	<u>AD-13</u>	Soil
D-8D Water Bar				Wa	ter Bar Not Insta	alled	
D-9D	0	2	1	1:1	4 Min 10	AD-15	Soil
D-10D	1	3.33	0.67	1.5:1	7 Min 50	AD-6, AD-3B, (part) AD-2B, AD-2C	D ₅₀₌ 4" Bedrock
D-11D	0	1	0.5	1:1	41 Min Near Vert.	Tipple Wash Hose	Grouted Rip-Rap
D-12D	0	1	0.5	1:1	81 Av.	Tipple Wash Hose	Soil
D-13D Water Shed	0	6	0.5	10:1 2:1	0.5 Av.	AD-6 Partial	Soil
D-14D	0	1.33	0.67	1.5:1	0.06Av.	AU-4A	Soil
D-15D	0	2.00	1.00	1:1	0.05 Av.	AD-16	Soil
D-16D	0	1.50	1.75	1:1	0.05 Av.	AD-18	Soil
D-17D	0	.96	1	1:1	0.08 Av.	AU-23, AD-20	Soil

Notes:

7-113 10/12/10

^{1.} Dimensions given indicate minimum requirements. Actual dimensions may vary. Minimum required cross-sections will be maintained.

^{2.} The use of lined drainage ditches is required when flow velocities exceed approximately 5 feet per second. Rip-rap may be installed where not required.

Table 7-25 Culvert Characteristics (Cont)

Culvert	Diameter (in.)	Туре	Contributing Watersheds	Slope (ft/ft)	Outlet Condition
C-1D	15	CMP flexible	AD-6, AD-3B	1.00	24" rip-rap
C-2D	15	CMP, RCP flexible	AD-2B, AD-2C, AD 3B AD-4, AD-6	4.0	10" rip-rap
C-3D	20	slt pipe	AD-3A	0.03	4" rip-rap
C-4D	21	CMP	AD-3A, AD-5, AD-7, AD-14, C-1OD	0.18	9" rip-rap
C-5D	18	CMP	AD-34, AD-5, AD-7, AD-9	0.07	<u>3"</u> rip-rap
C-6D	12	CMP	AD-b	0.48	9" rip-rap
C-7D	18	CMP	Abandoned In Place		
C-8D			Replaced with	C-SD	
C-9D	18	CMP	See C-8D	0.05	3" rip-rap
C-10D	18	CMP	Tipple Wash Hose	0.03	Soil
C-11D	12	CMP flexible	AD-4A	0.05 0.25	3" rip-rap
C-12D	8	CMP	AD-18	0.05	Soil
C-13D	12	СМР	AU-23, AD-20	0.07	Soil
<u>C-14D</u>	<u>18</u>	CMP	<u>AD-13</u>	.02	Soil

coal storage pad, will be regraded to allow the drainage to flow into ditch D-7D below the fans shown on Plate 2-4C. At this point, the storage pad is level with D-7D, allowing drainage to easily flow into the ditch. The berm around the coal storage pad will prevent drainage over the edge of the pad and direct the flow toward ditch D-7D. The point at which the storage pad intersects D-7D is outside of the angle of repose of the coal pile, and the ditch will not be plugged by coal spillage. A catch basin exists just below this point which will trap any coal fines which may be washed into the drainage, protecting ditch D-7D below this point.

Ditch D-8D Water Bar

During October of 2010 as part of a response to NOV-10068, it was discovered that the Ditch D-8D water bar was never constructed, and therefore, references to it on applicable Plates and Permit text have been removed.


In-1996, Co Op observed that erosion problems existed which were associated with the water bar conveying runoff from Ditch D-8D to the inlet of Sediment Pond "B" as a result of water associated with the Water Truck. In order to eliminate these problems, the water bar and associated channel will be grouted using an 8" concrete slab. This will prevent the channel from eroding. Figure 7-15 shows a typical cross-section of the concrete crossing. A steel bridge structure and swell provides vehicle crossing as shown in the figure. The bridge is designed so that the water bar design cross-section is maintained passing under it.

Culvert C-40U

A trash and a debris clean out basin will be placed at the entrance to culvert C-40U. Additionally while constructing the Tank Seam Portal C.W. Mining will investigate other methods that can be incorporated to reduce the possible culvert C-40U becoming plugged by debris.

Figure 7-15 Ditch D-8D Water Bar Concrete Structure*

*Water bar was never constructed.



Typical Cross-Section

Minimum Channel Depth = 0.67' Minimum Required Depth = 0.33'

7-138 10/12/2010

This page intentionally left blank

Culvert Characteristics (cont'd)

Culvert	Diameter (in.)	Туре	Contributing Watersheds	Peak Q (cfs)	Slope (ft/ft)	Outlet Condition
C-1D	15	CMP flexible	AD-6, AD-3B	0.93	1.00	24" rip-rap
C-2D	15	CMP, RCP flexible	AD-2B, AD-2C, AD 3B AD-4, AD-6	1.47	4.0	10" rip-rap
C-3D	20	slt pipe	AD-3A	0.23	0.03	4" rip-rap
C-4D	21	CMP	AD-3A, AD-5, AD-7, AD-14, C-10D	2.66	0.18	9" гір-гар
C-5D	18	CMP	AD-34, AD-5, AD-7, AD-9	0.23	0.07	<u>3"</u> rip-rap
C-6D	12	CMP	AD-b	0.62	0.48	9" rip-rap
C-7D	18	CMP	Aband	oned In	Place	
C-8D			Replac	ed with	C-5D	
C-9D	18	CMP	See C-8D	2.36	0.05	3" rip-rap
C-10D	18	CMP	Tipple Wash Hose	0.25	0.03	Soil
C-11D	12	CMP flexible	AD-4A	.35	0.05 0.25	3" rip-rap
C-12D	8	CMP	AD-18	0.55	0.05	Soil
<u>C-13D</u>	<u>12</u>	<u>CMP</u>	<u>AU-23, AD-20</u>	0.99	0.07	Soil
<u>C-14D</u>	<u>18</u>	CMP	<u>AD-13</u>	1.23	.02	Soil

All culverts were evaluated for adequacy using Flowmaster (Haestad Methods, Inc.) or SedCad

4. The flow to culverts were taken as the summation of flows from each contributing watershed

(not accounting for flow routing). Thus, assumed flows are conservatively high.

Assume — η = .024 for CMP & flexible culverts η = .015 for RCP & Steel pipe

Flowmaster and SedCad printouts are shown on the following pages.

All culverts are designed to pass the design flows without overtopping. Comparisons of outlet velocity with channel stability were made using the figure on page 53. The maximum permissible velocity corresponding to the appropriate channel slopes were used (1:1, 2:1 etc.).

Velocities of 5.0 ft/s and less were considered non-erosive.

Where riprap is to be placed at the culvert outlet, it should extend a minimum distance of 3D50 - 5D5 downstream from the culvert outlet. The required riprap for each culvert is shown in the tables on pg. 49-51.

Culvert C-14D

Culvert Inputs:

Length (ft)	Slope (%)	Manning's n	Max. Headwater (ft)	Tailwater (ft)	Entrance Loss Coef. (Ke)
50.00	2.00	0.0240	1.00	0.00	0.50

Culvert Results:

Minimum pipe diameter: 1 - 10 inch pipe(s) required

Culvert installed = 18" diameter

Detailed Performance Curves

Design Discharge = 1.23 cfs

Maximum Headwater = 1.00 ft

(BOLD indicates design pipe size)

Headwater	Discharge (cfs)	Discharge (cfs)	Discharge (cfs)
(ft)	(8 in)	(10 in)	(12 in)
0.10	0.39	0.65	0.28
0.20	0.41	0.69	0.29
0.30	0.44	0.73	0.35
0.40	0.47	0.77	0.53
0.50	0.49	0.80	0.74
0.60	0.64	0.86	0.97
0.70	0.82	1.00	1.19
0.80	0.92	1.25	1.42
0.90	0.95	1.45	1.76
1.00	0.99	1.57	2.10
1.10	1.02	1.69	2.43
1.20	1.05	1.81	2.67
1.30	1.09	1.91	2.90
1.40	1.12	1.97	2.99
1.50	1.15	2.02	3.09



No Rip Rap Required

DITCH CHARACTERISTICS

DITCH	CHANNEL SLOPE %	CONTRIBUTING WATERSHED	PEAK Q(cfs)	BANK AND BOTTOM DESC.	MANNING 'S n ^(a)
D-1D	2 Min, 11 Max	AD-3A	0.23	Rocky Soil	0.03
D-2D	6 Min, 20 Max	AD-3A, AD-5	0.53	Rocky Soil, Bedrock	0.03
D-3D		Replaced with C-5D			
D-4D	2 Min, 7 Av 17 Max	AD-14	0.05	Soil	0.03
D-5D		Replaced with C-5D			
D-6D	2 Min, 4 Max	AD-3A, AD-5, AD-7 AD-9, AD-10, AD-12 AD-14	3.63	Rocky Soil	0.03
D-7D	2 Min, 6 Av 55 Max	AD-1A, AD-1B, AD- 2A AD-2B, AD-2C, AD-3B AD-4, AD-6, AD-8	4.90	Soil D ₅₀ = 3"	0.03 0.033
D-8D	2 Min, 7 Max	AD-13	1.23	Soil	0.03
D-8D Concrete	2 Min	<u>AD-13</u>	1.23	Concrete	.015
D-8D Water Bar		Water Bar No	ot Installed		
D-9D	4Min, 10 Max	AD-15	1.20	Soil	0.03
D-10D	7 Min, 50 Max	AD-6, AD-3B, AD-2C	1.03	D ₅₀ = 4"	0.033
D-11D	41 Min Near Vertical Max	TIPPLE WASH HOSE	0.25	Grouted rip-rap	0.035
D-12D	81 Av.	TIPPLE WASH HOSE	0.25	Grouted	0.03
D-13D Water Bar	0.5 Av.	AD-6 Partial	0.23	Soil	0.03
D-14D	0.06 Av.	AU-4A	0.35	Soil	0.03
D-15D	0.05 Av.	AD-16	1.24	Soil	0.03
D-16D	0.05 Av.	AD-18	0.55	Soil	0.03
D-17D	0.08	AU-23,AD-20	0.99		

Ditch D-8D (Concrete Lined)

Material: Concrete

Trapezoidal Channel

Bottom Width (ft)	Left Sideslope Ratio	Right Sideslope Ratio	Slope (%)	Manning's n	Freeboard Depth (ft)	Freeboard % of Depth	Freeboard Mult. x (VxD)
1.50	1.0:1	1.0:1	2.0	0.0150	0.30		

	w/o Freeboard	w/ Freeboard
Design Discharge:	1.23 cfs	
Depth:	0.18 ft	0.48 ft
Top Width:	1.86 ft	2.46 ft
Velocity:	3.99 fps	No rip-rap required
X-Section Area:	0.30 sq ft	
Hydraulic Radius:	0.151 ft	
Froude Number:	1.74	



Ditch D-8D Concrete Crossing Structure

Concrete Demolition

Volume = (35 ft) (12 ft) (0.67 ft) = (281.4 cu ft) / 27 = 10.4 cu yd

Cost = (\$ 12.78/cu yd) (10.4 cu yd) = \$ 133

Time = (10.4 cu yd) / (45 cu yd/day) = 0.23 days

02220 875-5550 (Concrete Disposal on Site) 002315-400-1300 (3 CY loader) 02320-200-0320

(16 ton truck)

Volume = (10.4 cu yd) (1.3 swell-factor) = 13.5 cu yd

Cost = (\$ 10.69/cu yd) (13.5 cu yd) = \$ 144

Time = (13.5 cu yd) / (232 cu yd/day) = 0.06 days

Cost Subtotal \$ 277

Time Subtotal 0.29 days

Ditch D-8D Concrete Apron (installed 9/2010)

Concrete Demolition

Volume = (20 ft) (4 ft) (0.5 ft) = (40 cu ft) / 27 = 1.5 cu yd

Cost = (\$ 12.78/cu yd) (1.5 cu yd) = \$ 20

Time = (1.5 cu yd) / (45 cu yd/day) = 0.03 days

02220-875-5550 (Concrete Disposal on Site) 002315-400-1300 (3 CY loader) 02320-200-0320

(16 ton truck)

Volume = (1.5 cu yd) (1.3 swell factor) = 2.0 cu yd

Cost = (\$ 10.69/cu yd) (2.0 cu yd) = \$ 21.4

Time = (2.0 cu yd) / (232 cu yd/day) = 0.009 days

Cost Subtotal \$ 41.4 Time Subtotal .039 days

Ditch Flow Meter Box (installed 9/2010)

Concrete Demolition

Volume Concrete Walls = $\{(8 \text{ ft}) (6.2 \text{ ft}) (.67 \text{ ft})\} * 4 = (133 \text{ cu ft}) / 27 = 4.9 \text{ cu yd}$

Volume Concrete Floor & Ceiling = $\{(8.2)(6.2)(.67)\}$ *2 = (68 cu ft)/27 = 2.5 cu yd

Total Concrete Volume: 7.4 cu yd

Cost = (\$ 12.78/cu yd) (7.4 cu yd) = \$ 95.2

Time = (7.4 cu yd) / (45 cu yd/day) = 0.16 days

02220-875-5550 (Concrete Disposal on Site) 002315-400-1300 (3 CY loader) 02320-200-0320

(16 ton truck)

Volume = (7.4 cu yd) (1.3 swell factor) = 9.6 cu yd

Cost = (\$ 10.69/cu yd) (9.6 cu yd) = \$ 103

Time = (9.6 cu yd) / (232 cu yd/day) = 0.04 days

Cost Subtotal \$ 198 Time Subtotal .2 days

Lump Coal Storage Pad

Concrete Demolition

Wall Volume = (38ft) (4ft) (1ft) + (80ft) (4ft) (1ft) = (472 cu ft) / 27 = 17.5 cu yd

Slab Volume = (38 ft) (80 ft) (0.67) = (2,027 cu ft) / 27 = 75.1 cu yd

Total Volume = 17.5 + 75.1 = 92.6 cu yd

Cost = (\$ 12.78/cu yd) (92.6 cu yd) = \$ 1,183

Time = (92.6 cu yd) / (35 cu yd/day) = 2.65 days

02220-875-5550 (Concrete disposal on Site) 002315-400-1300 (3 CY loader) 02320-200-0320 (16 ton truck)

Volume = (92.6 cu yd) (1.3 swell factor) = 120.4 cu yd

Cost = (\$ 10.69/cu yd) (120.4 cu yd) = \$ 1,287

Time = (120.4 cu yd) / (232 cu yd/day) = 0.52 days

Cost Subtotal \$ 2,470

Time Subtotal 3.17 days